



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/20002BR0169/1

Work Order Type: Weatherization

Audit Name: 20002BR0169

CLIENT INFORMATION

Client Name:

Address:

Client ID: 20002BR0169

Alt. Client ID: Bradley

AGENCY INFORMATION

Agency: Bradley-Cleveland Community Services Agency

Agency Phone: (423) 479-4111

Address: P.O. Box 3297, 155 Sixth Street, S.E.
Cleveland, TN 37320

Fax: (423) 479-4113

Email Address:

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

Auditor
Sam Daugherty
865-207-0215

Client Name:

Client ID: 20002BR0169

Alt. Client ID: Bradley

Work Order (Bid Form)

Work Order Name: WO/20002BR0169/1

Report Run On: 5/24/2010

DOE Weatherization Assistant

Version 8.5.0

Page 1 of 7

Measures

Measure 1 access doors 2 each				Components			Inspected		
Comment fab 1access door to crawl space, install 32"x32" fab and install access door to crawl space 24"x24"							<input type="checkbox"/>		
#	Material / Labor	Description / Comment	Units	Estimated		Actual			
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
					<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
					<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total: <input type="text"/>		
Field Notes:									

Measure 2 attic insulation				Components			Inspected		
Comment 2032sqft blown cell. Could not get program to recommend add 7"							<input type="checkbox"/>		
#	Material / Labor	Description / Comment	Units	Estimated		Actual			
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
					<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
					<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total: <input type="text"/>		
Field Notes:									

Client Name:

Client ID: 20002BR0169

Alt. Client ID: Bradley

Work Order (Bid Form)

Work Order Name: WO/20002BR0169/1

Report Run On: 5/24/2010

DOE Weatherization Assistant

Version 8.5.0

Page 2 of 7

Measure 3 secure duct work**Components**

Inspected

Comment secure duct work from ground and re-attach boots☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1					

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Measure 4 wrap water heater**Components**

Inspected

Comment could not get program to recc.☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1					

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: 20002BR0169

Alt. Client ID: Bradley

Work Order (Bid Form)

Work Order Name: WO/20002BR0169/1

Report Run On: 5/24/2010

DOE Weatherization Assistant

Version 8.5.0

Page 3 of 7

Measure 6 Air Seal/Air Reduction**Components****Inspected**☐

Comment could get program to recommend this measure even tho reading on blower door eas 6871cfm, caulk the following ares- 96lnft of floor at centyer of home, closet ceilings, shelf in bathroom wall,doorway to utility room, plumbing at w/d , switchbox in utility room,. Drywall these areas, 2'x8' area in ceiling of closet at utility room, 2'x2' ceiling inpantry off of kit,hole in br closet ceiling less than 1sqft, replace w/s d-1, replace w/s and center seal @ d-2 and caulk around door, d-4 w/s , rpair broken pane @w-6, w-15&16 are storm windows only replace w/single pane to match existiing,

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1					

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total: **Sub Total:**

Field Notes:**Measure 7 Insulate 5 FT Pipe on Hot Water Heater****Components****Inspected**☐

Comment program would not recommend this needs to be done

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Hot Water Equipment	Insulate pipe	Linear Foot	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	Labor	Labor		1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total: **Sub Total:**

Field Notes:

Client Name:

Client ID: 20002BR0169

Alt. Client ID: Bradley

Work Order (Bid Form)

Work Order Name: WO/20002BR0169/1

Report Run On: 5/24/2010

DOE Weatherization Assistant

Version 8.5.0

Page 4 of 7

Measure 8 Mastic Duct boot / Return cavity (per boot)**Components****Inspected****Comment** 12 vents and 1 return☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
	Labor	Labor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	Other		Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:**Measure 9** Floor Insulation**Components****Inspected**

Comment program would not recommend this needs to be done
estimated costs program would not recommend measure, 736sqft R-19 batts
secure w/wire

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
	Labor	Labor		1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	Insulation	Floor Insulation	SqFt	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:

Client Name:

Client ID: 20002BR0169

Alt. Client ID: Bradley

Work Order (Bid Form)

Work Order Name: WO/20002BR0169/1

Report Run On: 5/24/2010

DOE Weatherization Assistant

Version 8.5.0

Page 5 of 7

Measure 10 Install Bathroom Exhaust Fan**Components****Inspected****Comment** Vent Unit to the Exterior
add 3 fans w/light☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Bathroom exhaust fan	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total: **Sub Total:** **Field Notes:****Measure 11 PressureRelief Piping Needed****Components****Inspected****Comment** program would not recommend this needs to be done☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Pressure relief piping	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total: **Sub Total:** **Field Notes:**

Client Name:

Client ID: 20002BR0169

Alt. Client ID: Bradley

Work Order (Bid Form)

Work Order Name: WO/20002BR0169/1

Report Run On: 5/24/2010

DOE Weatherization Assistant

Version 8.5.0

Page 6 of 7

Measure 12 Smoke Detector is Needed**Components****Inspected****Comment** 2 each 1 in each hallway☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Smoke detector	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 13 Vapor Barrier Needed
(Basement/Crawlspace)****Components****Inspected****Comment** Use 6 mil plastic.
Use 6 mil plastic.add 736sqft replace1296sqf of bad☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Basement / crawlspace vapor barrier	SqFt	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Work Order Grand Total:****Grand Total:**

Client Name:

Client ID: 20002BR0169

Alt. Client ID: Bradley

Work Order (Bid Form)

Work Order Name: WO/20002BR0169/1

Report Run On: 5/24/2010

DOE Weatherization Assistant

Version 8.5.0

Page 7 of 7